


4 Ersatzteilzeichnung - Spare parts drawing



Drehdornpresse - Arbor press - Ersatzteilliste - Spare part list							
Pos.	Bezeichnung	Description	Menge	Artikelnummer			
			Qty.	Item no.			
				DDP10	DDP20	DDP30	DDP50
1	Gusskörper	Casting	1	0335901001	0335902001	0335903001	0335901501
2	Label	Label	1		0335902002		
3	Positionsplatte	Position plate	1	0335900101	0335900201	0335900301	0335900501
4	Hebelstange	Lever rod	1	0335900104	0335900204	0335900304	0335901504
5	Knopf	Knob	2	0335900105	0335900205	0335900305	0335901505
6	Ritzel	Pinion	1	0335900105	0335900205	0335900305	0335901506
7	Platte	Plate	1	0335900112	0335900212	0335903007	0335901507
8	Spannplatte	Plate	1				
9	Gewindestift	Grub screw	3				
10	Stößel	Ram	1	0335900106	0335900206	0335900306	0335901510
11	Inbusschraube	Hexagon socket screw	4				
12	Sechskantschraube	Hexagon screw	1				
13	Zylinderstift	Cylindrical pin	1	6x20	6x20	6x20	6x20
14	Inbusschraube	Hexagon socket screw	4				
15	Stahlkugel	Steel ball	1	0335900115	0335900215	0335900315	0335901515
16	Feder	Spring	1	0335902016	0335902016	0335902016	0335901516
17	Gewindestift	Grub screw	1			0335900317	

DDP_parts.fm